



NOTE:
TREE DATA BASED ON OAK TREE ASSESSMENT BY JACK BRAZEAL ON 10.24.00.

NOTE:
ALL TREES OUTSIDE OF BUILDING ENVELOPE TO BE PROTECTED. TREES MAY BE REMOVED BY PERMIT IF NECESSARY FOR DRIVEWAY ACCESS BUT REMOVAL WILL BE MINIMIZED.

NOTE:
ALL TREE LOCATIONS WITHIN BUILDING ENVELOPE TO BE VERIFIED PRIOR TO PERMITTING

REV.	BY	DATE	DESCRIPTION

INDIVIDUAL SITE PLANS
SANTA YSABEL RANCH
COAL 99-0229
LOT 26

Lot 26				Must Save (visual mitigation)
Tree	Diameter	Type	Health	
1386	24	BLUE	72%	X
1387	10	BLUE	24%	X
1388	28	BLUE	36%	X
1389	24	BLUE	80%	X
1390	18	BLUE	76%	X
1391	22	BLUE	52%	X
1392	19	BLUE	60%	X
1393	48	BLUE	80%	X
1400	22	BLUE	52%	X
1401	28	BLUE	80%	X
1402	20	BLUE	80%	X
1403	35	BLUE	52%	X
1404	28	BLUE	80%	X

NOTE: ● = ORIGINAL DATA MODIFIED BY ALTHOUSE & MEADE, INC.