



Lot 71				
Tree	Diameter	Type	Health	Must Save (Visual mitigation)
216	12	BLUE	76%	X
217	20	BLUE	80%	X
218	13	BLUE	72%	X
219	22	BLUE	80%	X
220	23	BLUE	64%	X
221	19	BLUE	64%	X
222	23	BLUE	72%	X
223	23	BLUE	44%	X



REV.	BY	DATE	DESCRIPTION

NOTE:
 ALL TREE LOCATIONS WITHIN BUILDING ENVELOPE TO BE VERIFIED PRIOR TO PERMITTING

NOTE:
 ALL TREES OUTSIDE OF BUILDING ENVELOPE TO BE PROTECTED. TREES MAY BE REMOVED BY PERMIT IF NECESSARY FOR DRIVEWAY ACCESS BUT REMOVAL WILL BE MINIMIZED.

NOTE:
 TREE DATA BASED ON OAK TREE ASSESSMENT BY JACK BRAZEL ON 10.24.00.