

Lot 75				
Tree	Diameter	Type	Health	Must Save (visual mitigation)
△ 1234	18	BLUE	64%	
△ 1235	12	BLUE	64%	
△ 1236	16	BLUE	72%	
△ 1237	12	BLUE	48%	
△ 1239	12	BLUE	40%	
△ 2216	18	BLUE	52%	
△ 2217	19	BLUE	52%	
△ 2218	14	BLUE	64%	
△ 2219	8	BLUE	50%	
△ 2220	8	BLUE	32%	
△ 2221	6	BLUE	8%	
△ 2222	7	BLUE	20%	
△ 2223	8	SCRUB		
△ 2224	3	BLUE	4%	
△ 2225	9	BLUE	36%	
△ 2226	9	BLUE	36%	
△ 2227	10	BLUE	52%	
△ 2228	10	BLUE	24%	
△ 2229	6	BLUE	24%	
△ 2230	10	BLUE	56%	
△ 2231	10	BLUE	52%	
△ 2232	18	BLUE	68%	
△ 2233	28	BLUE	28%	
△ 2234	6	BLUE	32%	
△ 2235	21	BLUE	64%	
△ 2236	20	BLUE	24%	
△ 2237	6	BLUE	24%	
△ 2238	6	SCRUB		X
△ 2239	7	BLUE	48%	X
△ 2240	13	BLUE	52%	X
△ 2241	10	BLUE	32%	X
△ 2242	8	BLUE	32%	X
△ 2243	4	BLUE	4%	X
△ 2244	6	BLUE	12%	X
△ 2245	9	BLUE	28%	X
△ 2246	8	BLUE	32%	X
△ 2247	8	BLUE	28%	X
△ 2248	8	BLUE	28%	X
△ 2249	4	BLUE	24%	X
△ 2250	6	BLUE	32%	X
△ 2251	8	BLUE	32%	X
△ 2252	12	BLUE	48%	X
△ 2253	8	BLUE	40%	X
△ 2254	32	BLUE	60%	X
△ 2255	9	BLUE	36%	
△ 2256	8	BLUE	36%	
△ 2257	3	BLUE	4%	
△ 2258	10	BLUE	55%	
△ 2259	8	BLUE	55%	
△ 22534	14	BLUE	20%	
△ 22533	28	BLUE	30%	
△ 22532	15	BLUE	35%	
△ 22531	7	BLUE	20%	
△ 22530	52	BLUE	35%	
△ 22535	64	BLUE	35%	X
△ 22536	6	BLUE	20%	X
△ 22537	6	BLUE	20%	X
△ 22538	14	BLUE	40%	X
△ 22539	14	BLUE	25%	X
△ 22540	9 (3)	BLUE	30%	X

NOTE: ● = ORIGINAL DATA
 ● = MODIFIED BY
 ALTHOUSE
 & MEADE, INC.



INDIVIDUAL SITE PLANS
 SANTA YSABEL RANCH
 COAL 99-0229
 LOT 75



REV.	BY	DATE	DESCRIPTION
1		05.16.03	PER CONDITIONS

NOTE: ALL TREE LOCATIONS WITHIN BUILDING ENVELOPE TO BE VERIFIED PRIOR TO PERMITTING

NOTE: ALL TREES OUTSIDE OF BUILDING ENVELOPE TO BE PROTECTED. TREES MAY BE REMOVED BY PERMIT IF NECESSARY FOR DRIVEWAY ACCESS BUT REMOVAL WILL BE MINIMIZED.

NOTE: TREE DATA BASED ON OAK TREE ASSESSMENT BY JACK BRAZEL ON 10.24.00.

