


Lot 95			
Tree	Diameter	Type	Health
952	8	BLUE	40%
953	12	BLUE	24%
954	8	BLUE	28%
955	9	BLUE	24%
956	21	BLUE	48%
957	14	BLUE	40%
958	10	BLUE	24%
959	15	BLUE	32%
962	18	BLUE	40%
963	18	BLUE	40%
964	9	BLUE	28%
965	14	BLUE	20%
966	8	BLUE	16%
967	9	BLUE	32%
968	10	BLUE	36%
969	8	BLUE	16%
970	6	BLUE	12%
971	12	BLUE	56%
972	4	BLUE	4%
973	8	BLUE	28%
974	14	BLUE	64%
975	6	BLUE	60%
976	13	BLUE	72%
977	9	BLUE	32%
978	8	BLUE	8%
979	4	BLUE	8%
980	13	BLUE	36%
981	19	BLUE	24%
982	13	BLUE	36%
983	14	BLUE	0%
984	16	BLUE	76%
985	20	BLUE	56%
986	13	BLUE	48%
987	9	BLUE	24%
1901	9	BLUE	45%
1902	12	BLUE	30%
1903	9	BLUE	25%
1904	9	BLUE	35%
1905	7	BLUE	20%
1906	6	BLUE	10%
1907	14	BLUE	40%
1908	6	BLUE	25%
1909	18	BLUE	65%
2728	4	BLUE	20%
2729	5	BLUE	30%
2730	18	BLUE	40%
2731	10	BLUE	35%
2732	10	BLUE	40%



**INDIVIDUAL SITE PLANS
SANTA YSABEL RANCH
COAL 99-0229
LOT 95**



REV.	BY	DATE	DESCRIPTION

NOTE:
ALL TREE LOCATIONS WITHIN BUILDING ENVELOPE TO BE VERIFIED PRIOR TO PERMITTING

NOTE:
ALL TREES OUTSIDE OF BUILDING ENVELOPE TO BE PROTECTED. TREES MAY BE REMOVED BY PERMIT IF NECESSARY FOR DRIVEWAY ACCESS BUT REMOVAL WILL BE MINIMIZED.

NOTE:
TREE DATA BASED ON OAK TREE ASSESSMENT BY JACK BRAZEL ON 10.24.00.

